



Express Mail No: EQ 635923789 US

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of:

Timothy D. Reierson and H. Nicholas Riddle

Certificate

U.S. Patent No:

6,984,780

MAY 0 3 2006

Serial No:

10/625,446

of Correction

Filed:

July 22, 2003

For:

STRINGED INSTRUMENT FINGERBOARD WITH POSITION MARKERS

Group Art Unit:

2837

Examiner:

Hsieh, Shih Yung

Attorney Docket No: RE15.P01

Issued:

January 10, 2006

Certificate of Correction Branch

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

> April 28, 2006 Yakima Washington 98902

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT **UNDER 37 CFR 1.322**

Sirs:

Request is hereby made for a Certificate of Correction in the above noted U.S. Patent, as detailed in the attached Form PTO-1050 (two copies provided). An error was made by the Patent and Trademark Office (PTO), incorrectly listing only one inventor on the face of the published application. The published patent currently lists Timothy D. Reierson as sole inventor. In fact, Timothy D. Reierson and H. Nicholas Riddle are co-inventors, as properly noted and established in this patent's PTO file.

Additionally, the correction of a significant transcription error by the PTO, in column 19 of the application's specification is requested, as further detailed in the attached Form PTO-1050.

No fees are presently required to process this request. However, the Commissioner is authorized to charge PTO Customer Account 50-0269, if any fees are deemed necessary. Additionally, please send the approved Certificate of Correction to the address of the undersigned practitioner, associated with PTO Customer Number 21,792.

Respectfully Submitted,

Chris E. Svendsen, PTO Reg. No. 40,193

STRATTON BALLEW PLLC

213 South 12th Avenue

Yakima, WA 98902

Telephone (509) 453-1319 Facsimile (509) 453-4704

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _ 1 _ of _ 1

PATENT NO.

: 6,984,780 B2

APPLICATION NO.: 10/625,446

ISSUE DATE

: January 10, 2006

INVENTOR(S)

Timothy D. Reierson and H. Nicholas Riddle

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below.

Title page,

Item (76), "Inventor: Timothy D. Reierson, 6604 Appleview Rd., Yakima, WA (US) 98908" should read -Inventors: Timothy D. Reierson, 6604 Appleview Rd., Yakima, WA (US) 98908

H. Nicholas Riddle, 2400 St. Hilaire Road, Moxee, WA (US) 98936 -; and

Column 19.

Line 47, "B, B, A, D, G" should read -B, E, A, D, G -.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

STRATTON BALLEW PLLC 213 South 12th Avenue Yakima, WA 98902

This collection of information is required by 37 CFR 1.322, 1.323; and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.